

STATE OF MAINE  
DEPARTMENT OF CONSERVATION  
BUREAU OF PARKS AND LANDS  
BOATING FACILITIES DIVISION

NAVIGATIONAL AIDS - ANNUAL REPORT  
(To be submitted prior to December 31<sup>st</sup> each year)

NAME OF WATERBODY: Keoka Lake                      TOWN: Waterford                      COUNTY: Oxford  
Organization Name: Keoka Lake Association  
Street Address: P.O. Box 97                      City/Town: Waterford                      State: ME                      Zip: 04088

---

---

**Current Contact Information (as of 10/01/2024):**

Check here if there weren't any changes from last years' report

**President:** Brenda Hambleton                      **Phone #** (860) 729-2218  
**Mailing Address:** 41 Irene Drive  
**City:** Hollis                      **State:** NH                      **Zip:** 03049

**Vice President:** Jonathan Hasson                      **Phone #** (910) 987-1871  
**Mailing Address:** P.O. Box 45  
**City:** Waterford                      **State:** ME                      **Zip:** 04088

**Buoy Tender:** Andy Tabor                      **Phone #** (207) 838-9909  
**Mailing Address:** 33 Littlejohn Road  
**City:** Cape Elizabeth                      **State:** ME                      **Zip:** 04107

**Buoys were installed on:** 05/25/2024 \_\_\_\_\_

**Buoys were removed on:** 10/20/2024 \_\_\_\_\_

Please submit this form along with a copy of your inspection reports to:

Timothy Thurston  
Navigational Aids Supervisor  
1009 Brunswick Road  
Richmond, Maine 04357  
E-MAIL: [timothy.thurston@Maine.gov](mailto:timothy.thurston@Maine.gov)

or fax to: 207-582-2328

KLA Buoy Inspection Records – 2024 – Ice Out 04/03/2024

<u>Subject</u>	<u>Date</u>
Ordered additional chain for Hazard buoys	Fri 04/19/2024
Deployed loon nesting platform and 5 Loon Nest warning buoys.	Sat 05/25/2024
Installed Launch Ramp Dock, float, buoys & swim area line. 4 moorings had all their float bottles prop-struck and required deep dives to recover the chains: Swim A, R4, R6 & R8. R2 mooring was off station and was relocated. LEA Thermal Survey Buoy already on station.	Sat 05/25/2024
Relevelled one leg on the launch ramp dock that had not been tightened properly.	Tue 05/28/2024
Installed 3 illuminated Hazard buoys at the islands, Stone's Cove buoys, Dam buoys and float line. Installed the adapter plate and Sea-Lite LED module on the LEA buoy. The loon is on the nest!	Mon 06/10/2024
All KLA buoys and LEA buoy OK.	Mon 06/17/2024
All KLA buoys and LEA buoy OK.	Mon 06/24/2024
Loon nest broke its moorings and migrated down into Huvila Cove.	Wed 06/26/2024
Installed a steel anchor rod on the end of the Town Beach swim line.	Thu 06/27/2024
All KLA buoys and LEA buoy OK.	Mon 07/01/2024
Two loonlets hatched! Brought the loon nest over to our cottage for its first major refurbishment in 20 years.	Sat 07/06/2024
Removed the loon nest warning buoys. All other KLA & LEA buoys OK.	Sun 07/07/2024
All KLA buoys and LEA buoy OK.	Sat 07/13/2024
All KLA buoys and LEA buoy OK.	Fri 07/19/2024
All KLA buoys and LEA buoy OK.	Fri 08/02/2024
All KLA buoys and LEA buoy OK.	Sun 08/25/2024
All KLA buoys and LEA buoy OK.	Sun 09/01/2024
All KLA buoys and LEA buoy OK.	Sun 09/15/2024
All KLA buoys and LEA buoy OK	Tue 10/01/2024
Performed the repairs on the loon nest platform.	Wed 10/02/2024
Removed launch ramp dock, swim float & swim dock. Both the ladder brackets on the swim float ladder are broken. The cost to replace them looks like about \$146.	Sat 10/12/2024
Removed the island hazard buoys, Stone's Cove buoys & Dam buoys. Removed the LED module from the LEA buoy. Pulled the loon nest platform up onto the beach at Huvila Cove and tethered it to a tree. All other KLA buoys and LEA buoy OK.	Sun 10/13/2024
Removed remaining KLA buoys. LEA Thermal Survey buoy still on station. Ordered the replacement parts for the swim float ladder.	Sun 10/20/2024